



VECTOR ROTARY LATCH - INLINE BOTTOM PULL

Vector rotary latches offer concealed latch points with convenient push-to-close action. Vector Rotaries are suitable for a variety of applications that require high strength, robust and secure latching. They are employed either as single latch point or in a multipoint latching system. Available in either single or two stage latching. The two stage rotary offers a safety feature that securely latches a partially latched compartment. Specially engineered to offer minimized trigger release force that ensures smooth and easy opening.

Vector rotaries are combined with Vector actuators that connect to the rotary latch by Vector rods or cables, creating an optimized latching system with components easily and securely fitted together. Please see related products to choose your components for your complete Vector rotary latching system.



MATERIAL

Anti Vibration Bushing: TPE
Lagerbuchse: Polyamid glasfaserverstärkt (PA6GF30)
Cam: Edelstahl 316
Sicherungsclip: Stahl, verzinkt
Gehäuse: Stahl, verzinkt
Schließhaken: Zinc die cast, zinc plated or black powder coated
Hebel: Gehärteter Stahl, verzinkt



ÄHNLICHE PRODUKTE

Needed components for a complete system:

2-850, 2-745, 2-746, 2-835, 2-860

Ähnliche Produkte: 2-750-01, 2-750-03, 2-750-04, 2-750-07

Use the Index Code at industrilas.com




Industrilas
 — When access counts —

A product number is created by combining the figures in each column (AAAA-BBCDEFFG-HH)


AAAA Type		BB Material		C Type	D Type of jaw	E Mounting hole	FF Hebel	G Links / Rechts	HH Schließhaken
5223	Rotary for 9,4 mm striker	11	Stahl, verzinkt	1 Single stage	1 Single jaw	0 Through hole	02 Inline Bottom Pull	1 Recht	00 No striker
	Anti-BSR*			2 Double stage		1 M6 threaded		2 Links	01 With striker bolt UNC 5/16-18
5224	Rotary for 9,4 mm striker					2 UNC 1/4-20			02 With striker bolt M8
									03 With looped striker
									04 With riveted striker

* Anti-BSR means no Buzz, Squeak or Rattle due to TPE anti vibration bushing.



01



02



03



04

