






MATERIAL


Bracket: Steel, zinc plated Hinge: Zinc die cast, zinc plated, chrome plated or black texture powder coated Pin: Steel, zinc plated Threaded plate: Zinc die cast, zinc plated



Adjustable in the X- and Y-axis if used with adjustment parts and oversized mounting holes in the door. The hinge is mounted to a threaded plate previously attached to the inside of the door with a mounting bracket, temporarily taped to the door skin. The hinge can also be used without the adjustment parts, by using self-tapping screws. Universal right or left mounting.

Adjustment parts = Threaded plate with bracket (drawing C).







INDUSTRILAS.COM

P/N	Surface treatment	Adjustment Parts (C)	Drawing
321129	Zinc plated	Included	A+C
32112901	Zinc plated	Not included	А
321130	Zinc plated	Included	B+C
32113001	Zinc plated	Not included	В
321329	Chrome	Included	A+C
32132901	Chrome	Not included	А
321629	Black	Included	A+C
32162901	Black	Not included	А
321633	Black	Included	B+C
32163301	Black	Not included	В
321930	Chrome	Included	B+C
32193001	Chrome	Not included	В